SVHC BIZTONSÁGOS HASZNÁLATI ÚTMUTATÓ

A REACH KÜLÖNÖS AGGODALOMRA OKOT ADÓ (SVHC) ANYAGOKRÓL SZÓLÓ 33. SZÁMÚ CIKKE

Kedves Ügyfelünk!

A REACH rendelet (EK 1907/2006) 33(1) cikkelyének célja, hogy a szállított termékek vásárlói lehetőséget kapjanak azoknak a szükséges kockázatkezelési intézkedések a megtételére, amelyek az engedélyezendő anyagok legfrissebb listáján szereplő, különös aggodalomra okot adó (SVHC) anyagoknak az árucikkben való jelenlétéből fakadhatnak, garantálva ezzel azok biztonságos felhasználását.

A FORD támogatja általánosságban a REACH és konkrétan a 33(1) cikkely mögöttes célkitűzéseit, amelyek összhangban állnak termékeink felelősségteljes előállítására, kezelésére és felhasználására vonatkozó saját kötelezettségvállalásunkkal.

Az SVHC anyagok azonosítása

A részegységekben 0,1 tömegszázalék (w/w) feletti arányban jelen lévő SVHC anyagok az ellátási láncunkból származó tájékoztatáson és saját termékadatainkon alapuló legjobb tudásunk szerint megegyeznek a konkrét járművekre/alkatrészekre vonatkozó SVHC-listáinkban felsoroltakkal.

Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó specifikus adatok

Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó esetleg szükséges specifikus adatokat a konkrét járművekre/alkatrészekre vonatkozó SVHC-listáink tartalmazzák.

Az egyes árucikkek biztonságos felhasználására vonatkozó általános adatok

Minden FORD járműhöz tartozik kezelési útmutató, amely tartalmazza a jármű tulajdonosának, illetve üzembentartójának szóló, a biztonságos felhasználásra vonatkozó adatokat. Emellett a szervizszemélyzet számára a FORD járművek és gyári alkatrészek javításáról és szervizeléséről szóló tájékoztatója is tartalmaz biztonságos felhasználásra vonatkozó információkat.

A jármű alkatrészeiben esetleg jelenlévő, az illető járműre/alkatrészre vonatkozó SVHC-listán feltüntetett SVHC anyagokat olyan módon alkalmaztuk, hogy a felhasználókra minimális hatást gyakorolhassanak, az emberekre és a környezetre általuk jelentett veszély pedig kizárható legyen, amennyiben a járművet és alkatrészeit rendeltetésszerűen használják, továbbá az esetleges javításokat, szervizeléseket és karbantartásokat a rájuk vonatkozó műszaki utasítások betartásával és az iparágban bevált gyakorlat szerint végzik el.

Az élettartamuk végét elérő járművek az Európai Unióban csak erre jogosult hulladékkezelő (ATF) létesítményben helyezhetők el legálisan. A járműalkatrészeket a helyileg hatályos törvények és hatósági előírások betartásával kell hulladéklerakóba helyezni.

Modell: Ford Ranger

Az SVHC-lista az Európai Vegyianyag-ügynökség (ECHA) által vezetett, 2024. július 1.-jén érvényes jelöltlistán alapul

Az SVHC anyagokat tartalmazó árucikkek biztonságos felhasználására vonatkozó specifikus adatok

Nem szükséges külön felhasználási tájékoztatás – ezeknél a cikkeknél a biztonságos felhasználásra vonatkozó általános adatokat kell figyelembe venni.

| Commodity | REACH SVHCs |
|---|--|
| A/C Compressor | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Lead [7439-92-1] |
| A/C Lines, Receiver Drier and Accumulator | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] |
| | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Lead [7439-92-1] |
| ABS/ESC Module | 2-Methylimidazole [693-98-1] |
| | Lead [7439-92-1] |
| Accessories | 1,2-Dimethoxyethane [110-71-4] |
| | 1-Methyl-2-pyrrolidone [872-50-4] |
| | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Cobalt(II) nitrate hexahydrate [10026-22-9] |
| | Cobalt-sulfate-heptahydrate [10026-24-1] |
| | Diboron-trioxide [1303-86-2] |
| | Lead [7439-92-1] |
| Active and Air Suspension | TBBA [79-94-7] |
| Active Grille Shutter | Lead [7439-92-1] |
| Adaptive Cruise Control | Lead [7439-92-1] |
| Air Brakes | Lead [7439-92-1] |
| AIS - Air Cleaner and Low Pressure Ducts | 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] |
| | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| AIS - High Pressure Ducts | Dodecamethylcyclohexasiloxane [540-97-6] |
| | Lead [7439-92-1] |
| Alternator | Lead [7439-92-1] |
| Antenna | Lead [7439-92-1] |

| Appliques (Pillar, Decklid, Roof) | Lead [7439-92-1] |
|---|---|
| Audio and Navigation Head Units | Lead [7439-92-1] |
| Axle | Lead [7439-92-1] |
| Battery | Lead [7439-92-1] |
| | Lead-monoxide [1317-36-8] |
| Body Moldings - Roof Rack | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione |
| 3. | [2451-62-9] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Lead [7439-92-1] |
| Body Side InteriorTrim (Hard | Lead [7439-92-1] |
| Trim) | |
| Body Structure - Floor Pan - Front Floor and Side Sill | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Diboron-trioxide [1303-86-2] |
| | Lead [7439-92-1] |
| Bodyside, Wheel Arch, Rocker Moldings | C,C'-azodi(formamide) [123-77-3] |
| | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8] |
| | Lead [7439-92-1] |
| Brake - Parking | Diboron-trioxide [1303-86-2] |
| Brake Actuation | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Lead [7439-92-1] |
| Brake Tubes and Hoses | Lead [7439-92-1] |
| Brakes - Caliper & Anchor Brkt Assy (Front, Rear) | Lead [7439-92-1] |
| Brakes - Drum (Front/Rear) | Lead [7439-92-1] |
| Charge Air Cooler | Octamethylcyclotetrasiloxane [556-67-2] |
| Clutch / DMF (Dual Mass Flywheel) | Lead [7439-92-1] |
| Combined Sensing Module | 1,2-Dimethoxyethane [110-71-4] |
| | Lead [7439-92-1] |
| Console Floor/Rear | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| | Lead [7439-92-1] |
| Cooling - Transmission Oil Cooler | Cobalt(II) nitrate hexahydrate [10026-22-9] |
| Cooling Fans | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| Cooling Hoses & Bottles | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Lead [7439-92-1] |
| Door Handles | Lead [7439-92-1] |
| Dressed Engines Module | Imidazolidine-2-thione [96-45-7] |
| | Lead [7439-92-1] |
| Driveshaft(s) | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | |

| EDS Wiring Assembly & Components | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
|---|---|
| | Boric acid [10043-35-3] |
| | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| Electro/Mechanical Devices | Lead [7439-92-1] |
| Electro/Mechanical Devices - | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| Security | 1 |
| Electronic Control Panel and CCH | Lead [7439-92-1] |
| Electronic Modules - Amplifiers | Lead [7439-92-1] |
| Electronic Modules - Door Zone | Lead [7439-92-1] |
| Electronic Modules - Headlamp | Lead [7439-92-1] |
| Electronic Modules - Power Decklid/Liftgate (PLG) | Lead [7439-92-1] |
| Electronic Modules - Suspension | TBBA [79-94-7] |
| Electronic Modules - SYNC | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| Engine Water Pumps | Lead [7439-92-1] |
| Evaporator and Blower | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| Assemby (HVAC Module) | |
| | Hexahydromethylphthalic-anhydride [25550-51-0] |
| | Lead [7439-92-1] |
| | Nonylphenol [25154-52-3] |
| Exhaust Cold End (Muffler & | Disodium tetraborate, anhydrous [1330-43-4] |
| Output Pipe Assembly) | |
| | Lead [7439-92-1] |
| Exhaust Hot End (Catalytic Convertor) | Decamethylcyclopentasiloxane [541-02-6] |
| Exterior Cargo Mgmt | Lead [7439-92-1] |
| Exterior Lighting - Supplemental | Lead [7439-92-1] |
| FEAD | Lead [7439-92-1] |
| Front / Rear Door Trim | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| Fuel Door | Lead [7439-92-1] |
| Fuel Filler Pipes | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Lead [7439-92-1] |
| Fuel Injection | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| | Lead [7439-92-1] |
| Fuel Lines | Decamethylcyclopentasiloxane [541-02-6] |
| | Lead [7439-92-1] |
| Fuel Tanks | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Lead [7439-92-1] |
| | <u>, , , , , , , , , , , , , , , , , , , </u> |

| Headlamp / Side Marker | 1,6,7,8,9,14,15,16,17,17,18,18- |
|---|---|
| | Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9] |
| | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol |
| | [3147-75-9] |
| | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one |
| | [71868-10-5] |
| | Lead [7439-92-1] |
| Headliner / Sunvisor | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol |
| | [3147-75-9] |
| | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Cobalt-sulfate-heptahydrate [10026-24-1] |
| | Diboron-trioxide [1303-86-2] |
| | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8] |
| | Lead [7439-92-1] |
| I/S Mirror | Lead [7439-92-1] |
| Instrument Cluster | Lead [7439-92-1] |
| Interior Lighting | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| | Lead [7439-92-1] |
| IP Finish Panels/Registers | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one |
| | [71868-10-5] |
| | Octamethylcyclotetrasiloxane [556-67-2] |
| IP Substrate and Ducts | Imidazolidine-2-thione [96-45-7] |
| | Lead [7439-92-1] |
| | Refractory ceramic fibres [142844-00-6] |
| Latches - Side Door/Latch Mini Module | Decamethylcyclopentasiloxane [541-02-6] |
| | Lead [7439-92-1] |
| Locks | Lead [7439-92-1] |
| Main Floor Carpet | Lead [7439-92-1] |
| Mirrors | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8] |
| | Lead [7439-92-1] |
| | Silicic acid, lead salt [11120-22-2] |
| Park Assist | Lead [7439-92-1] |
| PATS Transceiver | Lead [7439-92-1] |
| PCV System | Lead [7439-92-1] |
| Pedal Box | Lead [7439-92-1] |
| Pedestrian Alert System (PAS) | Dicyclohexyl-phthalate [84-61-7] |
| | Lead [7439-92-1] |
| PEM | Lead [7439-92-1] |
| Plastic Bumpers and Fascias | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| Powertrain Control Module (PCM/EEC/ ECM) | C,C'-azodi(formamide) [123-77-3] |

| | Lead [7439-92-1] |
|---|--|
| PT Mounts | Dodecamethylcyclohexasiloxane [540-97-6] |
| PT Sensors | Lead [7439-92-1] |
| Rain and Daylight Sensor | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9] |
| | Lead [7439-92-1] |
| Restraint Electronics | Lead [7439-92-1] |
| Retainer Plate Spare Wheel | Lead [7439-92-1] |
| Sealing - Glass Runs and Belt Moldings | Bumetrizole [3896-11-5] |
| Seat Belts (Front and Rear) | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Lead [7439-92-1] |
| Seats - Foam - Cut and Sew | Bumetrizole [3896-11-5] |
| Seats - JIT | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| | Alkanes, C14-17, chloro [85535-85-9] |
| | Bumetrizole [3896-11-5] |
| | C,C'-azodi(formamide) [123-77-3] |
| | Diboron-trioxide [1303-86-2] |
| | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| | Tris(2-methoxyethoxy)vinylsilane [1067-53-4] |
| Shifter Cables/Brackets - Auto | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| | 4,4'-Isopropylidenediphenol [80-05-7] |
| | Lead [7439-92-1] |
| Shock Absorbers | Lead [7439-92-1] |
| Smart Junction Box & Body Control Module (SPDJB) | Lead [7439-92-1] |
| Speakers / Tweeters | Melamine [108-78-1] |
| | N,N-Dimethylacetamide [127-19-5] |
| Steering Column | Lead [7439-92-1] |
| Steering Gear and Linkage | Imidazolidine-2-thione [96-45-7] |
| | Lead [7439-92-1] |
| Steering Wheel, Drive Air Bag | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8] |
| | Lead [7439-92-1] |
| Switches - General Use | Lead [7439-92-1] |
| Switches - Headlamp. Window & Door | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |
| | Bumetrizole [3896-11-5] |
| | Lead [7439-92-1] |
| Switches - Steering Column | Lead [7439-92-1] |
| Taillamp / Redundant | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9] |

| | Diboron-trioxide [1303-86-2] |
|--|--|
| | Dicyclohexyl-phthalate [84-61-7] |
| | Octamethylcyclotetrasiloxane [556-67-2] |
| Temperature Sensors - Climate | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9] |
| | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5] |
| Tires | Lead [7439-92-1] |
| TPMS | Dodecamethylcyclohexasiloxane [540-97-6] |
| | Lead [7439-92-1] |
| Transfer Case (RWD) | Lead [7439-92-1] |
| Transmission - Auto | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Boric acid [10043-35-3] |
| | Cobalt-dinitrate [10141-05-6] |
| | Lead [7439-92-1] |
| | TBBA [79-94-7] |
| Transmission (Auto) - Solenoids & Sensors | Dodecamethylcyclohexasiloxane [540-97-6] |
| Wheel | 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9] |
| Window Regulator | C,C'-azodi(formamide) [123-77-3] |
| | Lead [7439-92-1] |
| Wiper Assembly (Rear, Front) & Washer System | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Lead [7439-92-1] |
| xEV - DCDC | Lead [7439-92-1] |
| xEV - eDrive | Lead [7439-92-1] |
| xEV - Traction Battery (as Shipped) | Lead [7439-92-1] |
| xEV - Traction Battery Charging | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3] |
| | Diboron-trioxide [1303-86-2] |
| | Lead [7439-92-1] |
| | TBBA [79-94-7] |